April 22, 2016

United States Environmental Protection Agency Air Compliance Branch 290 Broadway, 21st Floor New York, NY 10007-1866

Attn: NESHAP COORDINATOR

Re: GEORGE WASHINGTON BRIDGE, ADMINISTRATION BUILDING

OPERATOR PROJECT#: 417.798

Dear Madam/Sir:

Our courtesy re-notification for the asbestos abatement work to be done at the above referenced location is attached. Please note that the starting date has changed.

If you have any questions, please contact me at 201-595-4881.

Sincerely,

Uday Mehta, Manager

Environmental field Operations
Construction Management Division

Cc:

Project File (EPA-2441) RACM Notification File

UM/fl

U.S. Environmental Protection Agency Notification of Demolition and Renovation

Operator Project #: 41	7.798 Postmark:		Date Received: 0	3/25/2016	Notification #:	EPA-24	41		
. Type of Notification (O=Original R=Revised C=Canceled) O / 1									
II. Facility Information (Identify owner, removal contractor, and other operator)									
Owner Name:	THE PORT AUTHORITY OF NY & I	NJ							
Address:	241 ERIE ST. ROOM 236								
City:	JERSEY CITY	te: NJ	Zip: 07310						
Contact:	U. MEHTA, MANAGER, ENVIRON	MENTAL FIELD OP	S	Telephone:					
Removal Contractor: B&N&K RESTORATION CO. INC									
Address:	223 RANDOLPH AVENUE						,		
City:	CLIFTON State: NJ Zip: 0				Zip: 07011	: 07011			
Contact:	ALEKSANDER KURIDZA Telephone: 973-478-4681						4681		
Other operator:	N/A								
Address:									
City:	State: Zip:								
Contact:	Telephone:								
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency)									
	IV. Is Asbestos Present? (Yes/No) YES								
		umber, floor, and	l /or room numb	er):					
V. Facility Description (include building name, number, floor, and /or room number): Building Name: GEORGE WASHINGTON BRIDGE - ADMINSTRATION BUILDING									
Address:	220 BRUCE REYNOLDS BLVD								
City:	FORT LEE	Coumbin							
Site Location:	TOTAL ELECTRONICATION PUBLICATION PUBLICAT								
Building Size: Present Use:	ADMINISTRATION BUILDING	Prior Use: ADMINISTRATION BUILDING							
		opropriate, Used							
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: POLARIZED LIGHT MICROSCOPY - PLM									
VII. Approximate An	nount of Asbestos, Including:		RACM to Be Removed	Nonfriable Asbestos Materials					
1. Regulated	ACM to be Removed	Non-RACM To Be Removed		Not To Be	e Removed	Indicate			
2. Category I	ACM Not Removed ACM Not Removed			Cat I	Cat II	Measuremen	surement		
Pipes FITTIN	IGS / BOILER ROOM. BASEME		500 SQ. FT			Lnft:	500		
Surface Area TANK	INSULATION		750 SQ.FT			Sqft:	750		
Vol RACM Off Facility	y Component					Cuft:	0		
VIII. Scheduled Da	VIII. Scheduled Dates Asbestos Removal Start: 04/25/2016 Complete: 10/15/2016						<u> </u>		
IX. Scheduled Dates Demo\Renovation Start: Complete:									

U.S. Environmental Protection Agency Notification of Demolition and Renovation

EPA-2441

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used: RENOVATION OF HEATING SYSTEM UPGRADE								
XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos At the Demolition And Renovation Site: NEGATIVE PRESSURE METHOD AND WET METHOD WILL BE USED								
XII. Waste Transporter #1								
Name:	TWO BROTHERS CONTRACTING. INC							
Address:	250 RUTHERFORD BLVD	y						
City:	CLIFTON	State: NJ	Zip: 07014					
Contact:	SAVA MLADENOVIC		Telephone: 973-779-4300					
Waste Tran	sporter #2							
Name:	N/A							
Address:								
City:		State:	Zip:					
Contact:			Telephone:					
XIII. Waste Dis	posal Site							
Name:	GRAND CENTRAL SANITARY LANDFILL							
Location:	910 W. PENNSYLVANIA AVE							
City:	PENN ARGYL	State: PA	Zip: 18072					
	e:610-863-1399							
XIV. If Demolit	XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below							
Name:		Title:						
Authority:								
Date of O	Date of Order: Date Ordered To Begin:							
XV. For Emergency Renovations								
Date and Hour of Emergency:								
Description of Sudden or Unexpected Event:								
Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:								
XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder: IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS								
XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection (Signature of Owner/Operator) (Date)								
XVIII. I Cerify T	XVIII. I Cerify That the Above Information Is Correct. (Signature of Owner/Operator) (Date)							